



Vehicle History Report #: 64399841

Report Date: September 17, 2025 | 3:16 p.m. EDT

Report Status: Complete

2016 VOLKSWAGEN GOLF SPORTWAGEN S

Wagon | 4 Cylinders | Gas
3VWC17AU9GM505477
Country of Assembly: Mexico
Last Reported Odometer: 149,059 KM



Accident/Damage Records Found

Last Registered In:
Manitoba (Normal)

17 Service Records Found



No U.S. History Found



1 Open Recall Found



Not Actively Declared Stolen



No Import/Export Records Found

Questions? We're here to help.

Visit us at support.carfax.ca

This vehicle history report is based on **information** (<https://www.carfax.ca/vehicle-history-data>) that was reported and available to CARFAX Canada as of September 17, 2025 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report



Accident/Damage

INCIDENT DATE	DETAILS	AMOUNT
⚠ 2016 Oct 27	Winnipeg, Manitoba, Canada Estimate: Not Available Estimate Date: 2017 Jul 24	\$745.98
⚠ 2016 Oct 28	Winnipeg, Manitoba, Canada Estimate: Right Side Estimate Date: n/a Claim: Collision Right Side	\$745.98 Not Reported
⚠ 2016 Nov 24	Winnipeg, Manitoba, Canada Estimate: Not Available Estimate Date: 2016 Nov 28 Claim: Collision Left Rear	\$1,437.84 Not Reported
⚠ 2017 Jul 11	Winnipeg, Manitoba, Canada Estimate: Left Side Estimate Date: 2017 Jul 24 Claim: Collision Left Side	\$1,924.59 Not Reported
⚠ 2017 Oct 9	Winnipeg, Manitoba, Canada Estimate: Not Available Estimate Date: 2017 Oct 10	\$5,561.97
⚠ 2017 Oct 10	Winnipeg, Manitoba, Canada Claim: Collision Front	Not Reported
⚠ 2018 Jul 31	Manitoba, Canada Estimate: Left Side Estimate Date: n/a Claim: Vandalism Left Side	\$290.01 Not Reported
⚠ 2018 Nov 28	Manitoba, Canada Estimate: Vandalism Estimate Date: n/a Claim: Vandalism	\$334.66 Not Reported
⚠ 2020 Feb 13	Winnipeg, Manitoba, Canada Estimate: Rear Center Estimate Date: 2020 Feb 24 Claim: Collision Rear	\$1,176.49 Not Reported



Registration

 This vehicle has been registered in the province of **Manitoba** in **Canada** with **Normal** branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2015 Dec 24		Go Auto Haus Volkswagen Winnipeg, Manitoba, Canada	Vehicle serviced <ul style="list-style-type: none"> Pre-delivery inspection completed Battery/charging system checked Engine oil heater installed Radio code retrieved
2016 Oct 25	7,878 KM	Go Auto Haus Volkswagen Winnipeg, Manitoba, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Recommended maintenance performed
2016 Dec 27	10,198 KM	Go Auto Haus Volkswagen Winnipeg, Manitoba, Canada	Vehicle serviced <ul style="list-style-type: none"> Anti-theft/keyless remote battery replaced
2017 Mar 24	16,076 KM	Go Auto Haus Volkswagen Winnipeg, Manitoba, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Recommended maintenance performed Tires rotated
2017 Dec 19	31,402 KM	Go Auto Haus Volkswagen Winnipeg, Manitoba, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Recommended maintenance performed Air filter replaced Battery/charging system checked Cabin air filter replaced/cleaned Oil and filter changed
2017 Dec 30		Go Auto Haus Volkswagen Winnipeg, Manitoba, Canada	Vehicle serviced <ul style="list-style-type: none"> Front door adjusted
2018 Jan 31	32,132 KM	Go Auto Haus Volkswagen Winnipeg, Manitoba, Canada	Vehicle serviced
2018 Aug 8	41,425 KM	Go Auto Haus Volkswagen Winnipeg, Manitoba, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Recommended maintenance performed
2019 Jan 30	51,736 KM	Go Auto Haus Volkswagen Winnipeg, Manitoba, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Recommended maintenance performed Doors checked
2020 Feb 18		Go Auto Haus Volkswagen Winnipeg, Manitoba, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Recommended maintenance performed Brakes checked
2020 Aug 14	73,980 KM	Go Auto Haus Volkswagen Winnipeg, Manitoba, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Recommended maintenance performed Brakes checked
2022 Jan 4	92,343 KM	Go Auto Haus Volkswagen Winnipeg, Manitoba, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Brakes checked Oil and filter changed Rear wiper blade replaced
2023 Jan 6	109,289 KM	Go Auto Haus Volkswagen Winnipeg, Manitoba, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Axles checked Brakes checked Fluids checked

ODOMETER	SOURCE	DETAILS
		<ul style="list-style-type: none"> • Oil and filter changed • Tire condition and pressure checked
2023 Jun 19	118,884 KM Go Auto Haus Volkswagen Winnipeg, Manitoba, Canada	Vehicle serviced <ul style="list-style-type: none"> • Maintenance inspection completed • Recommended maintenance performed • Brakes checked • Four tires balanced • Oil and filter changed • Rear wheel bearing(s)/hub(s) replaced
2024 Dec 9	139,417 KM Maxim Muffler & Auto Winnipeg, Manitoba, Canada	Vehicle serviced <ul style="list-style-type: none"> • Blower motor replaced/repaired
2025 Jan 31	141,048 KM Vip Lube - Ellice Winnipeg, Manitoba, Canada	Vehicle serviced <ul style="list-style-type: none"> • Oil and filter changed
2025 Aug 7	149,059 KM Vip Lube - Ellice Winnipeg, Manitoba, Canada	Vehicle serviced <ul style="list-style-type: none"> • Oil and filter changed



Open Recalls

Recall #: 20UF | SUCTION JET PUMP Recall Date: 2024 Feb 16

Recall Description

The suction jet pump inside the fuel tank is designed to purge fuel from the Evaporative Emissions (EVAP) system. If a specific seal inside an affected suction jet pump fails, the fuel may flow directly into the EVAP system. If this happens, fuel could accumulate in the EVAP system and may leak through the charcoal canister filter element. Leaking fuel, in the presence of an ignition source, may result in a fire.

Remedy

Replace the suction jet pump.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact VOLKSWAGEN or visit [Volkswagen's website](#).

(<https://www.vw.com/en/owners-and-services/about-my-vehicle/recalls.html>)



Stolen Vehicle Check

✓ This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2015 Dec 24		Go Auto Haus Volkswagen Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2016 Jun 16		Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Vehicle colour noted as gray

ODOMETER	SOURCE	RECORD TYPE	DETAILS
2016 Jul 31	Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as gray
2016 Oct 25	7,878 KM Go Auto Haus Volkswagen Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2016 Oct 28	 Winnipeg, Manitoba, Canada	Collision	Right Side
2016 Oct 28	Insurance Records Winnipeg, Manitoba, Canada	Collision	Estimate Date: n/a Right Side
2016 Nov 24	Insurance Records Winnipeg, Manitoba, Canada	Estimate Repair	Estimate Date: 2016-11-28 Not Available
2016 Nov 24	9,479 KM Winnipeg, Manitoba, Canada	Collision	Left Rear
2016 Dec 27	10,198 KM Go Auto Haus Volkswagen Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2017 Mar 24	16,076 KM Go Auto Haus Volkswagen Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2017 Jul 11	 Insurance Records Winnipeg, Manitoba, Canada	Estimate Repair	Estimate Date: 2017-07-24 Left Side
2017 Jul 11	23,356 KM Winnipeg, Manitoba, Canada	Collision	Left Side
2017 Jul 24	23,358 KM Insurance Records Winnipeg, Manitoba, Canada	Estimate Repair	Incident Date: 2016-10-27 Not Available
2017 Jul 31	Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as gray
2017 Oct 9	 Insurance Records Winnipeg, Manitoba, Canada	Estimate Repair	Estimate Date: 2017-10-10 Not Available
2017 Oct 10	27,789 KM Winnipeg, Manitoba, Canada	Collision	Front
2017 Dec 19	31,402 KM Go Auto Haus Volkswagen Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2017 Dec 30	 Go Auto Haus Volkswagen Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2018 Jan 31	32,132 KM Go Auto Haus Volkswagen Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2018 Jul 31	 Manitoba, Canada	Vandalism	Left Side
2018 Jul 31	Insurance Records Manitoba, Canada	Vandalism	Estimate Date: n/a Left Side
2018 Jul 31	Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed

ODOMETER	SOURCE	RECORD TYPE	DETAILS
		Vehicle colour noted as gray	
2018 Aug 8	41,425 KM Go Auto Haus Volkswagen Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2018 Nov 28	Vandalism Manitoba, Canada		
2018 Nov 28	Insurance Records Manitoba, Canada	Vandalism	Estimate Date: n/a
2019 Jan 30	51,736 KM Go Auto Haus Volkswagen Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2019 Jul 31	Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as gray
2020 Feb 13	67,589 KM Winnipeg, Manitoba, Canada	Collision	Rear
2020 Feb 18	Go Auto Haus Volkswagen Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2020 Feb 24	67,590 KM Insurance Records Winnipeg, Manitoba, Canada	Estimate Repair	Incident Date: 2020-02-13 Rear Center
2020 Jul 31	Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as gray
2020 Aug 14	73,980 KM Go Auto Haus Volkswagen Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2021 Jul 31	Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as gray
2022 Jan 4	92,343 KM Go Auto Haus Volkswagen Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2022 Jul 31	Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as gray
2023 Jan 6	109,289 KM Go Auto Haus Volkswagen Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2023 Jun 19	118,884 KM Go Auto Haus Volkswagen Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2023 Jul 31	Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as gray
2024 Feb 16	VOLKSWAGEN	Recall	Manufacturer Recall Issued Recall # 20UF
2024 Jul 31	Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as gray

ODOMETER	SOURCE	RECORD TYPE	DETAILS
2024 Dec 9	139,417 KM Maxim Muffler & Auto Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2025 Jan 31	141,048 KM Vip Lube - Ellice Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2025 Jul 31	Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as gray
2025 Aug 7	149,059 KM Vip Lube - Ellice Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2025 Sep 10	Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Vehicle colour noted as gray



Questions? We're here to help.

Visit us at support.carfax.ca

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada.

© 2025 CARFAX Canada ULC. All rights reserved.

